

ADEQ Complaints and Inspections

Computer Services Division

Patrick Stair - (501) 682-0673

Search Form

Please make your selection(s), then click the "Search" button. All fields left "blank" or "No Restrictions" returns the complete list. AFIN, Permit Number, Facility Name, Insp/Complaint number, Name/Address and City are matched if the record contains what you enter. The Miscellaneous Search field matches on a "contains" search against the Complaint/Inspection description, Complaint/Inspection location, Complaint/Inspection Comment, and Name/Address fields in the master record. All other fields are matched if the record equals what you enter.

Complaint/Inspection Information

Insp/Complaint
Number:

Search Type
 Complaints

Name/Address:

Inspections

County:

Both

City:

Inspections With Violations

Miscellaneous Search:

Facility/Permit Information

AFIN:

(Must enter dash, XX-XXXXX)

Permit
Number:

(Digits, Letters, & Dashes only)

Media:

[Facility and Permit Information \(PDS\)](#)

Date Range

Start
Date:

(mm/dd/yyyy)

End
Date:

(mm/dd/yyyy)

Search

Reset

Download

[Download a zipped copy of the full Access 2000 Database](#)
(CompInsp_web.zip Approximate file size: 14.5 MB)

Note: These data files are updated nightly.

Complaints and Inspections

AFIN	Permit Number	Comp/ Insp No.	Name/Address	Date	Media
Recs Found: 10	<u><<</u> <u><</u>	Page 1 /1 <u>></u> <u>>></u>	Records Per Page: <u>1</u> <u>5</u> <u>10</u> <u>20</u> <u>30</u> <u>40</u> <u>50</u> <u>100</u>	Export Query	
15-00000		059956 (I)	Southwestern Energy Byers-Isom 09-16 #3-29H5 County: Conway	6/13/2011	WS

INSPECTION COMMENT: Permitting issues and Trash/Unauthorized materials in pits

15-00000	01051-WG-P	059040 (I)	Seeco Inc. Lanoy 8-16 #3, 4-22H16 PO Box 789 Conway County: Conway	5/16/2011	WS
--------------------------	----------------------------	----------------------------	--	-----------	----

INSPECTION CONCERNS: Fay Shale 1.) As per Part II, Section B.1. of your permit; the Operator & other parties involved with drilling activities shall be prohibited from disposing into the pit any waste oil, hydraulic fluids, transmission fluids, frac fluids, trash or any other miscellaneous rig waste. The site's separators are connected to frac tanks & depositing "flowback water" into the site's reserve pit. Flowback water is residual frac fluid and is prohibited from being stored in reserve pits. 2.) As per Part II, Section B.4. of your permit; the pit shall contain only water-based drilling fluids generated during the drilling of the well or wells at the single location at which it is constructed. In the event of an emergency, the pit may be used for additional storage of water-based drilling fluids from the same or an adjacent site, provided that the event shall be reported to the Department immediately. The site's separators are connected to frac tanks & depositing "flowback water" into the site's reserve pit. The drilling rig has been offsite since April 1, 2011(per AOGC's Form 3 "Producer's Completion & Recompletion Report" for Drilling Permit# 43562 & 43563); and there was NO active drilling occurring during the inspection. In a letter dated April 27, 2011 Southwestern Energy was denied permission to use existing reserve pits for emergency temporary storage of prohibited fluids by ADEQ. INSPECTION COMMENT: Comments: There is a reserve pit onsite. The site's separators are connected to two frac tanks with hosing leading into the reserve pit. The Operator has been depositing flowback water into the reserve pit. The wells are currently producing & a produced water tank

AFIN	Permit Number	Comp/Insp No.	Name/Address	Date	Media
is onsite. The site is reclaimed & well-vegetated. No erosion issues were observed during the inspection.					
<u>15-00000</u>	<u>01530-WG-P</u>	<u>054422 (I)</u>	SOUTHWESTERN ENERGY CO. GEORGE SHEFFER P. O. BOX 789 CONWAY County: Conway	8/27/2010	WN
<u>15-00000</u>	<u>01537-WG-P</u>	<u>055214 (I)</u>	SOUTHWESTERN ENERGY COMPANY P. O. BOX 789 CONWAY County: Conway	10/14/2010	WS
<u>23-00000</u>		<u>039399 (I)</u>	Thompson 09-16#2-17H Southwestern Energy Production County: Faulkner	3/28/2008	WS
INSPECTION COMMENT: An on-site follow up was conducted on March 28. It was found that most of the fluids in the pit had been removed but the flow of fluids in the ephemeral stream had not decreased. Evidence of fluids was found in an unnamed tributary of Sucker Creek, approximately « mile downstream of the reserve pit.					
<u>23-00000</u>	<u>01462-WG-P</u>	<u>053772 (I)</u>	SOUTHWESTERN ENERGY P.O. BOX 789 CONWAY County: Faulkner	7/12/2010	WS
<u>23-01051</u>	<u>ARR153111</u>	<u>048711 (I)</u>	SOUTHWESTERN ENERGY	10/20/20	WN

AFIN	Permit Number	Comp/Insp No.	Name/Address	Date	Media
			W OF HWY 64 & FLEMING ST CONWAY County: Faulkner	09	

INSPECTION CONCERNS: 1. No Notice of Coverage posted at site entry. 2. No rain gauge installed at site. Required if inspections are conducted every 14 days and after every « inch rain event. Also during the inspection it was noted that the site map on-site did not indicate locations of equipment storage as required in Part II, Section A.4.G.6 of the permit. Mr. Gravengaard indicated that machinery would be stored on the site. The inspection was conducted on the second day of site activity and there was little equipment present at the site during the inspection. Mr. Gravengaard indicated that he would keep th

<u>42-00000</u>	<u>00294-WG-P</u>	<u>043291 (I)</u>	NEHUS #6-10H9 SOUTHWESTERN ENERGY CO 980 AIRPORT RD OZARK County: Logan	12/30/20 08	WS
-----------------	-------------------	-------------------	---	----------------	----

INSPECTION CONCERNS: 1. Evidence of an unauthorized discharge of drilling fluids to a nearby intermittent stream was observed, thus entering the waters of the State. This is a violation of Part I.A.5.a of your permit. 2. No sediment controls were in place at the site to prevent sediment from potentially entering a nearby, intermittent watercourse, otherwise defined as waters of the State. INSPECTION COMMENT: SOUTHWESTERN ENERGY

<u>42-00000</u>	<u>00604-WG-P</u>	<u>045726 (I)</u>	SOUTHWESTERN ENERGY COMPANY HARDGRAVE #2-11H 980 AIRPORT ROAD OZARK County: Logan	5/12/200 9	WS
-----------------	-------------------	-------------------	---	---------------	----

INSPECTION CONCERNS: Two small pools of what appeared to be drilling fluids found at base of pad. Indicated by higher conductivity. Cracks in the levee of the reserve pit were observed. Spillage of drilling chemicals in storage area.

<u>71-00000</u>	<u>01482-WG-P</u>	<u>054782 (I)</u>	SOUTHWESTERN ENERGY GEORGE SHEFFER P. O. BOX 789 CONWAY County: Van Buren	9/20/201 0	WS
-----------------	-------------------	-------------------	---	---------------	----

AFIN	Permit Number	Comp/ Insp No.	Name/Address	Date	Media



[**Send Us Feedback**](#)

[**Take our 1 Minute Web Survey**](#)



ADEQ Helpline: (501) 682-0923

[Privacy Statement](#)

[Legal Disclaimer](#)

[Accessibility](#)

[About PDF™](#)

©2010 Arkansas Department of Environmental Quality. All rights reserved.

[ADEQ Webmaster](#)